



3. Close the AC and turn it on. Also turn on the oscilloscope. Set the horizontal range to $\sim 10 \mu\text{s}$ or more.
4. Turn the gain of the AC on until noise appears on the oscilloscope.
5. Change the focus knob until you see a dip in the AC trace. The AC trace should look like an upside down Gaussian.
6. Fine tune the tilt, focus, polarization, and the knobs at I to get the best looking AC trace without saturating the detector. For 1550 nm, the tilt should be $\sim 3.55^\circ$. If the detector saturates, the minimum of your AC trace will no longer look like an upside down Gaussian, instead it will be a flat line. You'll get the best looking AC traces with the lowest gain settings, so make sure you optimize all variables.
7. Measure the FWHM of your AC trace. 1 ms on the oscilloscope trace translates to 9.9 ps in the optical domain. This value must be multiplied by 0.707 (1, 0.5) assuming that the pulse is a Gaussian (Square, Lorentzian).